

CASE STUDY

SIMPLE SOLUTION CURES REPEAT PUMP SHAFT BREAKAGES AT OIL REFINERY

- Cause of premature failures identified
- Solution required no modification to pump
- Improved MTBR



Refinery

CHALLENGE

A US oil refinery was experiencing issues with a barrel pump. They asked ClydeUnion Pumps to perform an upgrade and investigate the cause of numerous shaft breakages in the location of the thrust collar.

SOLUTION

Thrust shaft breakages can occur for a number of reasons: improper shaft design, excessive thrust loading, excessive runout of the shaft and/or thrust collar, or poor materials specification. In this instance, the intrinsic design was the root cause. The internal levelling washer had seized, forcing the thrust collar to cycle the shaft until it failed.

ClydeUnion Pumps swapped out the thrust bearing with one that has greater thrust pad flexibility, enabling the thrust collar to operate correctly. As the replacement had the same design envelope as the original, there was no need for further modification.

Industry: Oil & Gas – downstream

Region: Americas


Category: Mechanical design upgrade

API Type: BB5

ClydeUnion Pumps Aftermarket Technical Services team has experience across a range of services on critical rotating and reciprocating equipment to improve operational safety, reliability and efficiency. The drop-in replacement of two original Bryron Jackson pumps for the oil and gas market is one of our success stories documented in our library of case studies. These case studies highlight the requirement from the customer, how we achieved the goal and the process we followed to deliver the improvements.

OUTCOMES

The cause of the shaft breakages has been identified. A simple solution has been implemented that will improve Mean Time Between Repairs (MTBR) in future.



Bearing Number	JHN-7
3-Shoe Element Area (Net Sq. In.)	12.3
6-Shoe Element Area (Net Sq. In.)	24.5
JHN Bearing, complete	43
Spare Collar	12 1/2
6 Spare Shoes	6
B (Bore)*	2.500
C	7.375
E	1/2
F (Normal Size)*	7
H	2 3/8
JJ	3/16
K	1/4
L (Chamfer)	1/16
N	3/8
NN	7/16
P	3/8
Q	3 3/4
T	13/16
X	1 1/4
Y	7 1/8
Z	6 7/8

Bearing Number	JHJ-7
Area (Net Sq. In.)	24.5
J H Bearing, complete	30
JHJ Bearing, complete	47
Spare Collar	12 1/2
6 Spare Shoes	6
B (Bore)*	2.500
C	7.375
E	1/2
F (Normal Size)*	7
H	2 3/8
JJ	3/16
K	1/4
L (Chamfer)	1/16
N	3/8
NN	7/16
P	3/8
Q	3 3/4
T	13/16
X	1 1/4
Y	7 1/8
Z	6 7/8

Aberdeen Service Center
P: +44 1224 756 100

Abu Dhabi Service Center
P: +971 02 4081900

Anancy Service Center
P: +49 405 220 2401

Baton Rouge Service Center
P: +1 225 778 3310

Battle Creek Service Center
P: +1 269 966 4782

Burlington Service Center
P: +1 905 315 3813

Calgary Service Center
P: +1 800 352 8294

Corpus Christi Center
P: +1 361 371 6519

Downey Service Center
P: +1 562 622 2371

Glasgow Service Center
P: +44 141 637 7141

Jenks Service Center
P: +1 281 217 6359

Odessa Service Center
P: +1 704 808 3780

Penistone Service Center
P: +44 1226 763 311

Singapore Service Center
P: +65 6513 9276

Zhengzhou Service Center
P: +86 371 8665 2391

E: cu.sales@celerosft.com
www.celerosft.com



| SPEED | EXCELLENCE | PARTNERSHIP